

Bill Summary
1st Session of the 60th Legislature

Bill No.:	SB 358
Version:	INT
Request No.	1070
Author:	Sen. Boren
Date:	01/06/2025

Bill Analysis

SB 358 requires every operator of a train in the state to install a hot bearings detector system at least every 10 miles along each main line. The measure authorizes the Department of Public Safety to levy a fine of \$1,000.00-\$5,000.00.

Prepared by: Kalen Taylor